
















HIT-HY 200















-10°C...40°C / 14°F...104°F





HAS-D	d <sub>f</sub> [mm]	t <sub>fix</sub> [mm]	d <sub>0</sub> [mm]	h <sub>d</sub> [mm]	Δ [mm]	L <sub>t</sub> [mm]	SW [mm]	T <sub>inst</sub> [Nm]
M12x160	16	12...25	14	132	≥ 28	90	18/19*	30
M12x185	16	12...50	14	157	≥ 28	110	18/19*	30
M16x200	20	16...30	18	165	≥ 36	122	24	50
M16x220	20	16...50	18	185	≥ 36	138	24	50
M20x280	26	20...50	24	232	≥ 48	174	30	80









HIT-HY 200



-10°C...40°C / 14°F...104°F



HAS-D	d <sub>f</sub> [mm]	t <sub>fix</sub> [mm]	d <sub>0</sub> [mm]	h <sub>0</sub> [mm]	Δ [mm]	h <sub>ef</sub> [mm]	L <sub>p</sub>	SW [mm]	T <sub>inst</sub> [Nm]
M12x160	14	12...25	14	132 - t <sub>fix</sub>	≥ 28	125 - t <sub>fix</sub>	70 - t <sub>fix</sub>	18/19*	30
M12x185	14	12...50	14	157 - t <sub>fix</sub>	≥ 28	150 - t <sub>fix</sub>	90 - t <sub>fix</sub>	18/19*	30
M16x200	18	16...30	18	165 - t <sub>fix</sub>	≥ 36	155 - t <sub>fix</sub>	110 - t <sub>fix</sub>	24	50
M16x220	18	16...50	18	185 - t <sub>fix</sub>	≥ 36	175 - t <sub>fix</sub>	125 - t <sub>fix</sub>	24	50
M20x280	24	20...50	24	232 - t <sub>fix</sub>	≥ 48	220 - t <sub>fix</sub>	165 - t <sub>fix</sub>	30	80

